



## **BRT\_TN\_001**

# **FT93x Errata Technical Note**

**Version 1.0**

**Issue Date: 2017-03-07**

The intention of this errata technical note is to give a detailed description of known functional or electrical issues with the BRT FT93x devices.

Use of Bridgetek Pte devices in life support and/or safety applications is entirely at the user's risk, and the user agrees to defend, indemnify and hold Bridgetek Pte harmless from any and all damages, claims, suits or expense resulting from such use.

**Bridgetek Pte Ltd (BRT Chip)**

178 Paya Lebar Road, #07-03 Singapore 409030

Tel : +65 6547 4827 Fax : +65 6841 6071

Web Site: <http://brtchip.com>

Copyright © Bridgetek Pte Ltd

## **Table of Contents**

<b>1 FT93x Revision.....</b>	<b>2</b>
<b>2 Errata History Table – Functional Issues.....</b>	<b>3</b>
<b>2.1 Errata History Table – Electrical and Timing Specification Deviations .....</b>	<b>3</b>
<b>3 Functional Issues of FT93x .....</b>	<b>4</b>
<b>3.1 Revision B .....</b>	<b>4</b>
3.1.1 RTC Alarm can be missed under certain conditions .....	4
<b>4 Electrical and Timing Specification deviations of FT93x ..</b>	<b>5</b>
<b>5 FT93x Package Markings.....</b>	<b>6</b>
<b>6 Contact Information.....</b>	<b>7</b>
<b>Appendix A – List of Tables &amp; Figures .....</b>	<b>8</b>
List of Tables.....	8
List of Figures .....	8
<b>Appendix B – Revision History .....</b>	<b>9</b>

## 1 FT93x Revision

FT93x part numbers are listed in Table 1-1. The letter at the end of date code identifies the device revision.

The current revision of the **Rev B**, released **March 2017**. All known issues with this silicon revision are recorded in this Technical Note.

Part Number	Package
FT930Q	68 Pin QFN
FT931Q	56 Pin QFN

**Table 1-1 - FT93x Part Numbers**

This errata technical note covers the revisions of FT930Q listed in Table 1-2.

Revision	Notes
A	Never released
B	Second device revision (Release March 2017)

**Table 1-2 - FT930Q Revisions**

This errata technical note covers the revisions of FT931Q listed in Table 1-3.

Revision	Notes
A	Never released
B	Second device revision (Release March 2017)

**Table 1-3 - FT931Q Revisions**

## 2 Errata History Table – Functional Issues

Functional Errata	Short Description	Errata occurs in device revision
FT930Q	Real Time Clock (RTC) alarm interrupt can be missed under certain conditions	<b>Rev B</b>
FT931Q	Real Time Clock (RTC) alarm interrupt can be missed under certain conditions	<b>Rev B</b>

**Table 2-1 – Functional Issues**

### 2.1 Errata History Table – Electrical and Timing Specification Deviations

Deviations	Short Description	Errata occurs in device revision
-	No known issues	-

**Table 2-2 - Electrical and Timing Specification Deviations**

## 3 Functional Issues of FT93x

### 3.1 Revision B

#### 3.1.1 RTC Alarm can be missed under certain conditions

##### Introduction:

The FT93x RTC raises an interrupt request to the FT93x interrupt controller when any of the enabled interrupt conditions occur in the RTC. The RTC interrupts are enabled via RTC\_CTRL register. The RTC interrupt service routine checks RTC interrupt pending status by reading RTC\_STAT register and takes necessary action.

##### Issue:

1. The RTC interrupt may not be responded in certain conditions, for example when interrupts are globally masked in the FT93x interrupt controller or when the CPU core is in certain period while processing another interrupt.

##### Exception:

The issue doesn't affect another consequence that the RTC interrupt is also a wake-up source and when the system is in power down state, the RTC interrupt can wake up the system via the Power Management (PM) controller. Upon system wake-up, the PM interrupt service routine is executed first and the RTC interrupt is not serviced and consequently lost.

##### Workaround:

The workaround options are as follows:

1. When the system is in active mode, software shall use a timer to periodically check the RTC\_STAT bits. If RTC\_STAT indicates that status bits of enabled interrupts are set, then call the RTC interrupt service routine. The period to use shall be determined by the interrupt latency and processing requirements. If monitoring date and time interrupts (RTC\_STAT.AINT1 and RTC\_STAT.AINT2) only, then the timer period may be set to half a second because these alarms have a minimum period of 1 second.
2. When the system enters the powered down state, the periodic timer shall be disabled. If the RTC interrupt is enabled as a wake-up source, then software shall ensure that the RTC\_STAT bits shall be checked and processed immediately upon system wake-up right after PM NMI service routine has been processed.

##### Package Specific:

The affected packages are listed in Table 3-1.


Package	Applicable (Yes/No)
FT930Q	Y
FT931Q	Y

**Table 3-1 - Affected Packages**

## **4 Electrical and Timing Specification deviations of FT93x**

There are no known electrical or timing problems with any revision of silicon.

## 5 FT93x Package Markings



**Figure 5-1 - T93XQ Top Side**

### Notes:

1. FT93XQ symbol stands for FT930Q, FT931Q, FT932Q, and FT933Q.
2. YYWW = Date Code, where YY is year and WW is week number and following character B indicates the silicon revision B.
3. Marking alignment should be centre justified.
4. Laser marking should be used.

All marking dimensions should be marked proportionally. Marking font should be using standard font (Roman Simplex).

## 6 Contact Information

### Headquarters – Singapore

Bridgetek Pte Ltd  
178 Paya Lebar Road, #07-03  
Singapore 409030  
Tel: +65 6547 4827  
Fax: +65 6841 6071

E-mail (Sales) [sales.apac@brtchip.com](mailto:sales.apac@brtchip.com)  
E-mail (Support) [support.apac@brtchip.com](mailto:support.apac@brtchip.com)

### Branch Office – Taipei, Taiwan

Bridgetek Pte Ltd, Taiwan Branch  
2 Floor, No. 516, Sec. 1, Nei Hu Road, Nei Hu District  
Taipei 114  
Taiwan, R.O.C.  
Tel: +886 (2) 8797 5691  
Fax: +886 (2) 8751 9737

E-mail (Sales) [sales.apac@brtchip.com](mailto:sales.apac@brtchip.com)  
E-mail (Support) [support.apac@brtchip.com](mailto:support.apac@brtchip.com)

### Branch Office - Glasgow, United Kingdom

Bridgetek Pte. Ltd.  
Unit 1, 2 Seaward Place, Centurion Business Park  
Glasgow G41 1HH  
United Kingdom  
Tel: +44 (0) 141 429 2777  
Fax: +44 (0) 141 429 2758

E-mail (Sales) [sales.emea@brtchip.com](mailto:sales.emea@brtchip.com)  
E-mail (Support) [support.emea@brtchip.com](mailto:support.emea@brtchip.com)

### Branch Office – Vietnam

Bridgetek VietNam Company Limited  
Lutaco Tower Building, 5th Floor, 173A Nguyen Van  
Troj,  
Ward 11, Phu Nhuan District,  
Ho Chi Minh City, Vietnam  
Tel : 08 38453222  
Fax : 08 38455222

E-mail (Sales) [sales.apac@brtchip.com](mailto:sales.apac@brtchip.com)  
E-mail (Support) [support.apac@brtchip.com](mailto:support.apac@brtchip.com)

### Web Site

<http://brtchip.com/>

### Distributor and Sales Representatives

Please visit the Sales Network page of the [Bridgetek Web site](#) for the contact details of our distributor(s) and sales representative(s) in your country.

System and equipment manufacturers and designers are responsible to ensure that their systems, and any Bridgetek Pte Ltd (BRT Chip) devices incorporated in their systems, meet all applicable safety, regulatory and system-level performance requirements. All application-related information in this document (including application descriptions, suggested Bridgetek devices and other materials) is provided for reference only. While Bridgetek has taken care to assure it is accurate, this information is subject to customer confirmation, and Bridgetek disclaims all liability for system designs and for any applications assistance provided by Bridgetek. Use of Bridgetek devices in life support and/or safety applications is entirely at the user's risk, and the user agrees to defend, indemnify and hold harmless Bridgetek from any and all damages, claims, suits or expense resulting from such use. This document is subject to change without notice. No freedom to use patents or other intellectual property rights is implied by the publication of this document. Neither the whole nor any part of the information contained in, or the product described in this document, may be adapted or reproduced in any material or electronic form without the prior written consent of the copyright holder. Bridgetek Pte Ltd, 178 Paya Lebar Road, #07-03, Singapore 409030. Singapore Registered Company Number: 201542387H.



## Appendix A – List of Tables & Figures

### List of Tables

Table 1-1 - FT93x Part Numbers .....	2
Table 1-2 - FT930Q Revisions.....	2
Table 1-3 - FT931Q Revisions.....	2
Table 2-1 – Functional Issues .....	3
Table 2-2 - Electrical and Timing Specification Deviations .....	3
Table 3-1 - Affected Packages .....	4

### List of Figures

Figure 5-1 - T93XQ Top Side.....	6
----------------------------------	---

## Appendix B – Revision History

Document Title: BRT\_TN\_001 FT93x Errata Technical Note  
Document Reference No.: BRT\_000109  
Clearance No.: BRT#070  
Product Page: <http://brtchip.com/product/>  
Document Feedback: [Send Feedback](#)

Revision	Changes	Date
1.0	Initial Release	2017-03-07