

Date: 23th Apr, 2024

Bridgetek Pte Ltd

1 Tai Seng Avenue, Tower A, #03-05, Singapore 536464
Tel +65 6547 4827
www.brtchip.com

Notification # BRT_TN_005 / BRT_TN_006

Errata Notification for: BT815/816/817/818/817A/BT88x series

Dear [Distributors],			

This is a notification of a change to the documentation for BT81x / BT88x series that is currently offered by Bridgetek Pte Ltd.

We are reaching out to notify an important Errata that has been identified on our BT81x / BT88x series. This Errata pertains to specific user applications, which may affect the functionality or performance of the product under certain conditions.

Our engineering team has developed a solution to address the Errata, and we are committed ensuring the highest quality and reliability of our products. Details of the Errata along with the recommended solutions are provided as an attachment in this email.

Recommended Action: Provide Errata notice to customers for new projects (design stage) onwards.

The changes discussed within this notification are for your information only.

For questions regarding this notice, please contact our Field Sales Representative at sales.admin@brtchip.com

Yours Sincerely, PCN Team

Registered in Singapore Registration No.: 201542387H