

Bridgetek Pte Ltd

Bridging Technology

178 Paya Lebar Road, #07-04/05, Singapore 409030 Tel: (+65) 6841 1174 Fax: (+65) 6841 6071 E-Mail: <u>sales@brtchip.com</u> Web: <u>http://www.brtchip.com</u>

PCN Tracking Number: PCN_BRT_001

Issue Date: 2017-05-02

Product Change Notification

Product Part Number	FT930 devices: FT930Q, FT931Q, FT932Q, FT933Q	Estimated implementation date
Descriptio n of Change	Company logo changed in the chip marking.	Jun 2017
Reason for Change	Company logo changed from FTDI to Bridgetek.	
Detailed Descriptio n	Only change "FTDI" to "BRT" in the company logo	
Impact to Data sheet	Updated the data sheet for chip marking changed. <u>http://brtchip.com/wp-</u> <u>content/uploads/Support/Documentation/Datasheets/ICs/MCU/DS_FT93</u> <u>0 1 2 3.pdf</u>	
Benefit of Change	No change.	
Markings to distinguis h revised from:	The company logo changed, after the date code - 1727.	
Sample Availabilit y	Jul 2017	
Risk Assessme nt, Fit Form and Function & reliability	Fit: Dimension has not changed. Form: Visual appearance has not changed. Function: Functional silicon has not changed.	
PDF Download	http://brtchip.com/wp- content/uploads/Support/Documentation/PCNs/PCN_BRT_FT93x.pdf	
Others:		
-		